

SUMMARY



SITE	PERRY PARK	CZULEGER PARK	LILENTHAL PARK	FRANKLIN PARK	ANDERSON PARK
VISIBILITY	9	7	6	9	9
ACCESSIBILITY	8	7	8	7	7
DESIGN CANVAS	5	6	6	8	7
BARRIERS TO SHOVEL-READY	7	6	7	8	8
AMENITIES & INFRASTRUCTURE	9	6	7	9	9
IMPACT TO SURROUNDING ENVIRONMENT	5	5	5	8	8
<u>TOTAL SCORE</u>	<u>41</u>	<u>37</u>	<u>39</u>	<u>49</u>	<u>48</u>

- Sites ranked from 1 (worst) to 10 (best) for a total possible rank of 60
- “Barriers to shovel-ready” and “impact to surrounding environment” are ranked in terms of how minimal they are